Metal Surgery Milwaukee LTD

182 W. Oklahoma Ave. Building #23 Milwaukee, WI 53207 Phone 414-744-8313 Fax 414-744-8770 www.metalsurgery.com e-mail: metalsu@execpc.com

NORTHERN ENGINEERING DIVISION OF FRASER SHIPYARDS INC.

This 14-foot PTO quill shaft was damaged on bearing journals and seal diameters due to bearing/seal failure. Repair procedure consisted of re-cut centers; under cut to remove worn & total indicated run out on 4 different surfaces. Copper plate approx. .01 per side, machine, nickel-plate & grind to Mfg. specifications.



Shaft is plated with copper for build up & filling gouges from bearing failure. Also prepared for nickel plating



Using a flow through anode nickel plating is in process.



The quill shaft is set up in a lathe for rotation during plating process to obtain a uniform build up.



Plating repair is inspected & completed to Mfg. specifications.