Metal Surgery Milwaukee LTD 182 W. Oklahoma Ave. Building #23

182 W. Oklahoma Ave. Building #23 Milwaukee, WI 53207 Phone 414-744-8313 Fax 414-744-8770 www.metalsurgery.com e-mail: metalsu@execpc.com

PLATING CUMMINS ENGINE BLOCK ON-SITE



MINIMAL DISASSEMBLY IS REQUIRED IN REPAIRING THIS 16CYL CASE. (LEFT)

EROSION OF LOWER SLEEVE BORE RESULTS IN LEAKAGE FROM WATER JACKET. (BELOW)

(Lower left) ERODED AREAS ARE COPPER PLATED FOR BUILD UP.

(Lower right) COPPER PLATING WAS HAND FINISHED & PLATED WITH NICKEL TO MFG. SPECS. COMPLETING REPAIR.



