

Metal Surgery Milw. LTD 10/19/02

Tembec Canada
Inspection & Repair Report of
AC. Compressor Valute




Metal Surgery Milwaukee LTD

182 W. Oklahoma Ave. Building #23


Milwaukee, WI 53207

Phone 414-744-8313 Fax 414-744-8770

www.metalsurgery.com e-mail: metalsu@execpc.com



Foreign material enter the system causing impeller blades to self destruct resulting in this damage to Valute



Sections were layed out & removed by drilling



Form tools are used to size areas for stitches

Holes are drilled using fixture blocks

All stitches are dogged & studs are installed around the perimeter completely sealing repair area



Metal Surgery Milwaukee LTD

182 W. Oklahoma Ave. Building #23

Milwaukee, WI 53207

Phone 414-744-8313 Fax 414-744-8770

www.metalsurgery.com e-mail: metalsu@execpc.com

Metal Surgery. Milw Ltd 12/01/ 00

Job #????

Tembec Canada

A.C. Compressor Valute

Ref. P.O. #?????

