

Metal Surgery Milwaukee LTD


182 Oklahoma Ave. Building #23

Milwaukee, WI 53207

Phone 414-744-8313 Fax 414-744-8770

www.metalsurgery.com e-mail: metalsu@execpc.com

ELECTRIC SALES AND ENGINEERING ELECTRIC MOTOR ROTOR SHAFT JOURNAL



Bearing journal damaged after years of service. Plating is the best repair procedure on an assembled stator. There is no heat involved with this process assuring no damage to assembled unit. Using flow-thru anode, chemicals are pumped through a carbon while shaft is in rotation.

