

Metal Surgery Milwaukee LTD.

182 W. Oklahoma Ave. Building #23

Milwaukee, WI 53207

Phone# 414-744-8313 Fax# 414-744-8770

Email- metalsu@execpc.com Website- www.metalsurgery.com

Casting Repair

This casting was sent to Metal Surgery for a foot on the casting that broke off. This casting was cast iron material as most castings are that come through Metal Surgery's doors.



Metal Surgery does casting repairs on a daily basis. Castings that Metal Surgery repairs ranges from a couple pounds to 120,000 lbs., with lifting capacity of 176,000 lbs. Metal Surgery is ready for just about any size casting anyone can haul.

The casting pictured was gas welded after the foot was completely excavated and secured in place.



After the casting was completed, Metal Surgery X-rayed the casting. The X-ray came back with zero defects in the weld zone. Another success for Metal Surgery.